

0060

**From:** Wess Sorensen <WSorensen@archcoal.com>  
**To:** <jdefrees/r4\_m-l@fs.fed.us>, <pbaker@state.ut.us>, <phess@state.ut.us>  
**Date:** 8/31/00 12:47PM  
**Subject:** PHOTOS OF ROCK SHELTER ON 150 ACRES

The following photos were taken today 8/31/00 of the rock shelter on the 150 acre lease modification. The shelter was recently undermined with the longwall as planned. The roof has spalled in through out the shelter. The thickness at the center of the span is about 2 ft and feathers out towards the edges. The cracks shown in the photos are located about 1500 ft north of the shelter. While in the ravine, I could here the rocks buckling and breaking similar to an active cave line on a pillar section underground. I could not hear the popping when I was up on the sage brush flat.

Wess

ACT/041/002  
Incoming



ACT/041/002 Incoming  
Rock shelter 42SV2492



ACT/041/002

Rock shelter 42SV2492





ACT/041/002 Incoming

Rock shelter 412 SV 24 52



ACT/041/002 Incoming

Rock shelter 42SV2492





ACT/041/002 Incoming

8/31/00

Subsidence cracks on plateau  
above rock shelter 42SV2492



ACT/041/602 Increasing  
Rock shelter 4250 2492





ACT/041/002 Incoming  
Subsidence cracks on plateau above  
Rock shelter # 42502492





ACT/041/002 Incoming

8/31/00  
Evidence of subsidence on  
plateron above rock shelter  
42 SV 2492